US EPA RECORDS CENTER REGION 5

PRELIMINARY ASSESSMENT REASSESSMENT

FOR

CITY, STATE

SS ID NO.

TDD NO. PAN

CERCLIS SITE NAME ESSEX GROUP INC. - TRIANGLE PLASTICS

U.S. EPA ID MIDO 42433 458

F05-058711064 FM10243 SA

MARCH 1, 1988

Prepared for: U.S. ENVIRONMENTAL PROTECTION AGENCY HAZARDOUS SITE EVALUATION DIVISION

under Contract Number 68-01-7347

1
_

Preliminary Assessment Reassessement

### PRELIMINARY ASSESSMENT REASSESSMENT

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this document, this document and attachments are not to be released without prior approval of the United States Environmental Protection Agency (U.S. EPA).

This Preliminary Assessment (PA) Reassessment has been prepared by Ecology and Environment, Inc., or its subcontractor C.C. Johnson and Malhotra, P.C., under the Field Investigation Team (FIT) contract with the U.S. EPA (No. 68-01-7347). The purpose of this PA Reassessment is to supplement the completed PA Form 2070-12 with preliminary and projected Hazard Ranking System (HRS) scores using HRS 1 (40 CFR 300, July 16, 1982) criteria and provide factor values using the revised HRS 2 (Federal Register proposed date, April 1988) criteria.

The preliminary HRS 1 score has been computed using available file information. The projected HRS 1 scores have been computed assuming requisite data which will be collected during potential site inspection activities. The HRS 2 factor values have been computed using available file information. The HRS 2 factor value criteria were developed to reflect anticipated key HRS 2 scoring issues.

Using this information, the U.S. EPA will be able to prioritize site inspection activities. This PA Reassessment is not a work plan to perform site inspection activities and no field activities were performed by the FIT prior to preparing this document.

### A. GENERAL INFORMATION

CERCLIS Site Name: ESSEX Group Inc TRIANGLE PHIST	CS
Also Known As: Recently Known as Regal Plase	has
Formerly Known As:	
Address: 15 700 COMMON RD, ROSEVINE, MI 48	066
City: DETROIT	
County: MACOMB	
State: MI	
Zip Code: 48066	
U.S.EPA ID No: MI DO 424 33 458	
SS ID No.:	
TDD No.: 703 - 058711064	
PAN: FMI 0243 SA	
PA Completed By: T. PACHOWICZ - & (AGENCY)	DATE: 5-25-83
PA Reassessment Prepared By: M. PECENY Et E (FIT)	DATE: 5-10-88
PA Reassessment Reviewed By: (FIT)	
PA Reassessment Approved By:(FIT)	DATE:
U.S. EPA USE ONLY:	
PA Reassessment Reviewed by (US EPA)	DATE:
APPROVED; Recommend Screening Site Inspection.	
APPROVED; No Further Remedial Action Planned.	
REJECTED.	
COMMENTS:	

## B. SITE INFORMATION

SITE DESCRIPTION (type of operation, physical description, i.e., landfill);
Site is located in an industrial complex along the Cropback Hay within
the Sec 7, T.IN., E. 13 E in relatively flat forcein. Surrobding
by residential development withing a distance of about 5000
-1000 feet (Ref. 6)
The TR. Plastics manufactured (1967-1980) the plastic goods
the metal mords (indirect confoct). The cooling water was
disposed into sanitary seweral the site Owner of the TR. Pl.
was Essex group Inc. Plant was bought out by Regal Plantic
in 1980 - 1981 land operate recents.
is too for all specials actively.
SITE HISTORY (current or previous owner/operator; history of operations;
active/inactive/unknown; previous agency actions): TR PHSTIC OF FRATION
CALLSED IN 1980 (Ref. 7 19). PA was conducted in 1983 (Ref. 1);
Notification of Hos. Weste Site Under Fil, Section 103 was filed
in 619-88 (Ref. 23. waste water information was filed in 1973 (Paf. 3)
NADES parmit inspection by store was conducted in 1975 ( Ref. 4 and 5)
No needs for NPOES permit or presence of haz, waste was encounter
sixte and plant is owned by Regal Plastics and produces the
same time of moducts ( plantles for auto industra) as previously
TRIANGLE
1
DESCRIPTION OF POTENTIAL HAZARD (substances present or alleged; migration
pathways; targets): He papers that TRUBNER MASTIC did not release any hor. Substance
into environment ( with respect both observed or potential
release). No dato exists from cooline water disclarers analyses
1967- 1980), looking water was not indirect contact with
plastic material and was used exclusively for cooling
of injection metal molds, Therefore, He povelitial of woling
waster contemination is judged to be very low to will
Recently, Regal Ploshic dhesn't generate (Ref. 11) am noz. weste
and down't have any discharge or dispostly permitted by thate
asoline water qualit is sampled (in house) - Mef. 11
Data reviewed indicates no observed or podeutial conto mination
Jenvironment by hazard substances.
Figure(s) located on following page(s).
Not responsive

#### C. HRS 1- PRELIMINARY AND PROJECTED HRS SCORES

The preliminary and projected HRS 1 scores were computed using HRS 1 (40 CFR 300, July 16, 1982) criteria. HRS 1 score worksheets are located in Section 2.

PRELIMINARY HRS SCORE

(This score is based on existing file information that was obtained prior to the screening site inspection.)

S<sub>FE</sub>=\_\_\_\_\_S<sub>DC</sub>=\_\_\_\_

PROJECTED HRS SCORE FOR SCREENING SITE INSPECTION (SSI) (This score is based on the expected acquisition of information from the screening site inspection.)

S<sub>PE</sub>=\_\_\_\_ S<sub>DC</sub>=\_\_\_\_

PROJECTED HRS SCORE FOR LISTING SITE INSPECTION (LSI) (This score is based on the expected acquisiton of information from the listing site inspection.)

 $S_{H}=$   $S_{DC}=$ 

### D. HRS 2- FACTOR VALUE

The HRS 2 factor values were computed using the revised HRS 2 (Federal Register proposed date, April 1988) criteria. The HRS 2 factor values have been calculated using available file information. HRS 2 factor value worksheets are located in Section 3.

Factor	Factor Value	Observed Human Exposure (X)
Waste Characteristics	(100)	
Air Pathway	(100)	
Groundwater Pathway	(100)	
Surface Water Pathway	(100)	
On-site Pathway	(100)	
TOTAL HRS 2 FACTOR VALUE	(500)	

Hazard Ranking System 1
Score Worksheets

Hazard Ranking System 2 Factor Value Worksheets

### HRS 2- FACTOR VALUE

Factor	Factor Value	Observed <u>Human Exposure</u> (X)
Waste Characteristics	(100)	
Air Pathway	(100)	
Groundwater Pathway	(100)	<del> </del>
Surface Water Pathway	(100)	
On-site Pathway	(100)	
TOTAL HRS 2 FACTOR VALUE	(500)	

### WASTE CHARACTERISTICS

					Pactor
			Yes	Reference	Value
			(x)		
1.	(a)	Are CONTAINERS open, unsealed, or			
		non-intact?			(5)
	(b)	Is there evidence of contaminant			
	, - ,	migration away from the containers?			(5)
	(6)	Is the source(s) unlined or does it			\'-'
	(0)	have unsound diking?			(5)
		nave disound dixing?	—		
•	4-5	Date the TAMBETTY have supposed			
۷.	(4)	Does the LANDFILL have exposed			
		waste, or is the landfill uncovered	,		
		or is the landfill covered with			
		contaminated soil, non-intact cover			
		or cover less than 1 inch?			(5)
	(b)	Is there evidence of contaminant			
		migration away from the source?			(5)
	(c)	Is there an absence of a liner, a			
		run-on or runoff management system			
		or leachate collection and removal			
		system?		<del></del>	(5)
3.	(a)	Is the SURFACE IMPOUNDMENT wet			
		and non-enclosed?			(5)
	(b)	Is there evidence of contaminant			<del></del>
		migration away from the source?			(5)
	(c)	Is there no liner or diking?			(5)
		-			
4.	(a)	Is the PILE uncovered, or is the			
	•	pile covered with contaminated soil			
		non-intact cover or cover less than	=		
		1 inch?			(5)
	<b>(b)</b>	Is there an absence of a function-			
	ν.	ing run-on or runoff management			
		system or leachate collection			
					4.53
		system?		<del></del>	(5)
	(C)	Is there an absence of a liner?			(5)
_					
5.		y answer <u>highest</u> factor value			
		the following questions:			
	(a)	Is constituent data available			
		for waste?			(10)
	(b)	Is waste quantity as deposited			
		information available?			(8)
	(c)	Is disposal volume known?		<del></del>	(4)
	( <b>d</b> )	Is disposal area known?			(2)
			-		

...Continued

### WASTE CHARACTERISTICS (Continued)

 Complete the table for all sources at the site. Calculate Waste Quantity score and record summation to a maximum value of 30.

Source	Surface Area (ft2)	+	Divisor	-	Waste Quantity Score
Pile		+	85	_	
Drums/Non-drum Container		+	233	=	·
Surface Impoundment		+	375	_=	
Land Treatment		_	27,000	=	
Landfill		-	85,666	=	<del></del>
Contaminated Soil		+	1,125,000	=	

Total	 (30max)
Total Waste C	 (100)

### AIR PATHWAY

				<b>Pactor</b>
		Yes	Reference	<b>Value</b>
1.	Only assign factor value for (a) or (b),	(x)		
	choosing the higher value:			
	(a) Is there a residence or regularly			
	occupied building between 0 to 1/8			
	mile from a potential source(s)?			(25)
	(b) Is there a residence or regularly			<del></del>
	occupied building between 1/8 to 2			
	miles from a potential source(s)?			(5)
2.	Complete (a) and (b) and assign the			
	higher factor value:			
	(a) If documented contamination of air,			
	answer yes and assign factor value of 75.			(75
	(b) Calculate potential population and			
	assign factor value as given below:			

Distance (mile)	Population	×	Distance Weighting Factor	-	Subtotal
Onsite		×	1.682	-	
0-1/4		×	0.323	=	
1/4-1/2		×	0.056	-	
1/2-1		×	0.017	_	
1-2		×	0.005	=	
2-3		×	0.003		
3-4		×	0.002	-	

Total	 x_1_=	(75max)
	100	

Total	Air	Pathway	<b>Value</b>	 (100)

### GROUNDWATER PATEMAY

				Factor
		Yes	Reference	<b>Value</b>
		(x)		
1.	Is the depth to the aquifer of concern			
	less than 800 feet?			(5)
				<del>_</del>
2.	(a) Within 2 miles of the site,			
	is the geologic material between the			
	waste and the aquifer of concern			
	composed predominantly of sands, gravels	,		
	sandstone, limestone or dolomite?			(5)
	(b) Within 2 miles of the site,			
	is there evidence of a low hydraulic			
	conductivity layer (10 <sup>-6</sup> to 10 <sup>-9</sup> )between			
	the waste and the aquifer of concern?		<del></del>	(~15)
3.	Only assign factor value for (a) or (b),			
	choosing the higher value:			
	(a) is there a drinking water well(s) in the			
	aquifer of concern or a more shallow unit	t		
	0 to 1/2 mile from the source(s)?			(20)
	(b) Is there a drinking water well(s) in the			
	aquifer of concern or a more shallow unit	t		
	1/2 to 2 miles from the source(s)?			(5)
4.	Is the aquifer of concern a karst unit?			(10)
5.	Is the aquifer of concern a sole			
	source aquifer?			(5)
6.	Complete (a) and (b), and assign the higher			
	factor value:			
	(a) If documented contamination of drinking	ater		
	wells with TCL/TAL compounds, answer yes	and		
	assign a factor value of 50.			(50)
	(b) Calculate potential population and		<del></del>	<del></del>
	assign factor value as given below:			

Distance (mile)	Population	×	Distance Weighting Factor	_	Subtotal
0-1/4		×	0.25	=_	
1/4-1/2		×	0.16	=	
1/2-1		×	0.08	=	
1-2	<u> </u>	×	0.05	-	<u> </u>
2-3		×	0.03	-	
3-4		×	0.02	=	

Total <u>x1</u> = (50max)

### SURFACE WATER PATERNAY

				Factor
		Yes (x)	Reference	Value
1.	Does site lie within a 100-year or less			
	floodplain?		<del></del>	(5)
2.	Is there contamination attributable to the			
	site at a drinking water intake?	—		(20)
3.	Is this a sole-source surface water supply?		<del></del>	(10)
4.	Is a fishery (production) contaminated as a resu	lt		
	of the site, or is a fishery potentially impacte	đ		
	within 15 miles as a result of the site?			(5)
5.	Is a recreation area contaminated as a result of			
	the site, or is a recreation area potentially			
	impacted within 15 miles as a result of the site	7		(5)
6.	Is a sensitive environment contaminated as a			
	result of the site, or is a sensitive environmen	t		
	potentially impacted within 15 miles as a result			
	of the site?			(5)
7.	Complete (a) and (b), and assign the higher			
	factor value:			
	(a) If there is documented contamination of a			
	surface water intake with TCL/TAL compounds			
	within 15 miles as a result of the site,			
	answer yes and assign a factor value of 50.			(50)
	(b) Calculate potential population and assign a			
	factor value as given below:			

Intake	Population	x	Dilution Weighting Factor	=	Subtotal
<b>\$1</b>		×		2	
<b>#</b> 2		×		æ	
#3	<u> </u>	×		=	
		×		=	
		x		2	
		×		=	

<sup>\*</sup> Use table on following page.

Total	x_1 =	(50max)
	100	

### SURFACE WATER PATHWAY

# TABLE DILUTION WEIGHTING FACTORS

	Average Annual	
Surface	Flow in Cubic	Assigned
Characteristic	Feet per Second (CFS)	Value
Minimum perennial stream	Less than 5 cfs	2.5
Small to moderate stream	5 to 50 cfs	0.25
Moderate to large stream	Greater than 50 to 500 cfs	0.025
Large streams to rivers	Greater than 500 to 10,000 cfs	0.0013
Major rivers	Greater than 10,000 cfs	0.0003
Ocean or the Great Lakes	Not applicable	0.0003
Mixing zone of quiet flowing rivers	Greater than 50 cfs	0.125
Lakes, reservoirs	Add and average CFS of	Assign value
	tributaries flowing into	to calculated
	lake/reservoir.	CFS figure
		using above
		factors.

### ON-SITE PATHWAY

. .

						Yes (x)	Reference	Factor Value
1.	people liv	te located in we or go to so he source(s)? r NO to Questi	hool	within 1				(10)
2.	_	ith the remain	_	-				
		sidential or						(15)
3.	_	ublic use land		arriers?				(10)
4.	. Complete (a), (b) and (c), and assign the <a href="highest">highest</a> factor value: Which of the following are adjacent to site/source(s)							
	(a) School (b) Parks (c) Nation	inated from this, day-care, playgrounds, hal park, fedess, other publ	, re: oral	sidences endangered				(15) (10) (5)
5.		population value		in 1 mile of the s given below:	ite,			
	Distance (mile)	Population	x	Distance Weighting Factor	u	Subto	tal	
	0-1/4		×	0.05	ı			
	1/4-1/2		x	0.025				
-	1/2-1		×	0.0125	=			

TOTAL ON-SITE	PATHWAY	VALUE	(100)

Total \_\_\_\_\_(50max)

References

Ref.#	DESCRIPTION OF REFERENCE
1	Pielim. Assassment, Michigan TDO R5-8212-03A-243
	Essex group Inc, Roseville, MIDO 42433458
2	EPA-NOTIS DATA HING. SYSTEMS - HAZ. WASTE NOTIFI-
* 1	CATION 9-25-81
	,
3	WASTENATED DISCHARGE NOTIFICATION, STATE OF INI
	DEPT. ON NAT. RESOURCES, 1-1-1973
4	MI State, BNR, Bureau of Water Mag NPDES
	MI State, BNR, Bureau of Water Mag NPDES  parmit resuirement for Triangle Ploshe Dir Essex  zwup (Surface water discharge), 8-15-1974
	group (Surface water discharge), 8-15-1974
	(1)

TOD FOX OURTHOSY TRIANGUE PLASTICS

## REFERENCE DOCUMENTATION SHEET

Ref.#	DESCRIPTION OF REFERENCE
5	MI State, DAR, BW Mag. Site visit report on Triangle Plashes Site (for NPDES application)
	Triangle Plastics Site for NPDES application)
	4-10-1975
6	US95 Topo Map 7.5 min, Roseville
	go jo lojo moi jo 1.0 mm, 40sevine
Action	
li lor	
	<i>+1</i> 0 1 0 1 0 1
7	Telecomm. Revord, Sub: Essex group - info
	Telecomm Record
8	MI-State Environmental Health Dept. Subj:
	File info for Triangle Plostics

TOO FOUT-058711064 TRIANGLE PLASTICS

	HEFERENCE DOCUMENTATION SHEET
Ref.#	DESCRIPTION OF REFERENCE
9	Talecomm. Record, Cit of Rose ville. Subj.:
	Talecomm. Decord, Cit of Rose ville. Subj.: Cit file search on Triangle Plash'cs Dir.
	<u> </u>
10	telecomm. Devord, United Technology, Centemotive
	Div., Subj.: Triangle Ploshics-info VT was a owner or partner of Essex group
	Hill 4/88.
,	
//	Telecomm. Leverd, Regal Ploshies. Subj: Current 8'ste status and operation-info
	Sive status and sporation-info
	<u> </u>
	i

TOO FOT-058711064 DEIANGLE BLASTICS

## SOURCES AND DATES OF INFORMATION COLLECTION

SURCE	DAID
1) State Hazardous/Solid Waste Files 2) State Water Files 3) State Air Files 4) State Department of Health 5) State Geological Survey 6) State Department of Natural Resources 7) State Fire Marshall 8) County Department of Health 9) County Engineer 10) County Clerk/Recorder of Deeds 11) City Department of Health 12) City Engineer 13) City Fire Department/Fire Marshall 14) City Water/Sewer Department 15) U.S. Soil Conservation Service 16) Others	J-6/88 5/83 F-9/88
STATE CONTACT(S): Tim JASKi (name)	(3/3) 675 - 0860 (phone number) (phone number)



# ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415 International Specialists in the Environment

### MENORANDUM

DATE:	NOVEMBER 30, 1989
TO:	William Messenger, Chief Pre-Remedial Unit
FROM:	Jerome D. Oskvarek, FIT Office Manager
SUBJECT:	Transmittal Memorandum Identifying A Potential NFRAP
	Facility CERCLIS Site Name: ESSEX GROUP INC - IPIANGLE PLASTICS City: KOSEVILLE State: MICHIGAN
	U.S. EPA ID No.: MID042433458
	SSID No.:
	TDD No.: <u>F05-8711-064</u>
	PAN: FMIO2435A

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this memorandum, this memorandum and its attachments are not to be released without prior approval of the Untied States Environmental Protection Agency (U.S. EPA).

A work plan was tasked for the above-reference site; however, due to the HRS 1 preliminary and projected calculated scores, a work plan will not be prepared. The HRS worksheets are attached to this memorandum.

SI035(3/29/89)

Exemption 5 Deliberative Process 1 page removed

#### COMMENTS

The FIT would like to make the following additional comments concerning the site.

- 1. WITH THE EXCEPTION OF A FEW PRIVATE WELLS (GREATER THAN 2 MILES DISTANCE), MUNICIPALITIES WITHIN A 4 MILE RADIUS OF THE SITE PURCHASE THEIR DRINKING WATER FROM DETROIT.
- 2. AN OVERLAND MIGRATION ROUTE FROM THE SITE TO THE NEAREST SURFACE WATER IS APPROXIMATELY 4 MILES AND PROBABLY DOES NOT EXIST DUE TO PAVED ROADS.
- 3. PROSECTED HRS SCORE FOR LSI IS HIGH DUE TO WORST POSSIBLE SCENARIO FOR POTENTIAL RELEASE WHICH IS NOT ADDRESSED AT THE JSI STAGE. FURTHERMORE, CONSIDERING THE HEAVY INSUSTRY IN THE SITE VICINITY,

4. A POTENTIAL AIR RELEASE WOULD BE DIFFICULT TO ATTRIBUTE
TO THIS SITE ALONE.

5.

Exemption 5
Deliberative Process
2 pages removed

Exemption 5 Deliberative Process 15 pages removed

REFERENCE DOCUMENTATION SHEET		
Ref.£	DESCRIPTION OF REFERENCE	
1	Michigan Department of Public Health Water Well and Pump. Records, Sus. 24,	
	25, 33, 36, T. 2N., R. 12E. and Secs. 19, 20, 21,	
	22,24,26,27,32, T.2N., R.13E.	
2	V.S. Dipartment of Commerce, C.R. Smith, Secretary, Climatic Atlas of the United States, 1968.	
	Secretary Climatic Atlas of the United	
	Hallo, 1968.	
3	Bureau of Water Management and water	
	Resources Commission Memorandum to	
	NPDES pumil - short form C.	
4	Miscellaneous documents from FIT file information.	
	fele information.	

Ref.£	DESCRIPTION OF REFERENCE
5	Michigan Dipartment of Natural
	Municipal Water Withdrawals in
	Michigan p. 5, 32.
6	U.S.G. 5 Topographic Maps (1:24,000)
	Warren 1968 (p.r. 1983); Highland Park
	1968 (p.r. 1983); Mt. Clemens 1968 (p.r. 1983); Drosse Point 1968 (p.r. 1983).
1	11 5 . 1 . 5
+	An Tolechi Superintendent Warren City Waker Department, telephone con-
	Jusation with D. Tynch of E; Eon
	2/11/01.
8	A.C. Davango, Assistant Director
	Detroit Water Department, telephone
	on 2/9/87.

### REFERENCE DOCUMENTATION SHEET

Ref.#	DESCRIPTION OF REFERENCE
nei.	
9	Conversation with F Jantiela of E'E on 11/13/89 regarding possible
	E * E on 11/13/89 regarding possible
	compounds in plastics production
10	Telephone conversation with Time
	Payne - MDNR Ditroit Wildlife Division
	on 12/6/89. Contacted by 5. Johnson
	of E:E.



# ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415
International Specialists in the Environment

### MEMORANDUM

DATE:	NOVEMBER 30, 1989
TO:	William Messenger, Chief Pre-Remedial Unit
FROM:	Jerome D. Oskvarek, FIT Office Manager
SUBJECT:	Transmittal Memorandum Identifying A Potential NFRAP
	Facility CERCLIS Site Name: ESSEX GROUP INC IRIANGLE PLASTICS City: ROSEVILLE
	City: ROSEVILLE
	State: MICHIGAN
	U.S. EPA ID No.: MID042433458
	SSID No.:
	TDD No.: F05-8711-064
	PAN: FMIO2435A

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this memorandum, this memorandum and its attachments are not to be released without prior approval of the Untied States Environmental Protection Agency (U.S. EPA).

A work plan was tasked for the above-reference site; however, due to the HRS 1 preliminary and projected calculated scores, a work plan will not be prepared. The HRS worksheets are attached to this memorandum.

Exemption 5
Deliberative Process
1 page removed

#### COMMENTS

The FIT would like to make the following additional comments concerning the site.

- 1. WITH THE EXCEPTION OF A FEW PRIVATE WELLS (GREATER THAN 2 MILES DISTANCE), MUNICIPALITIES WITHIN A 4 MILE RADIUS OF THE SITE PURCHASE THEIR DRINKING WATER FROM DETROIT.
- 2. AN OVERLAND MIGRATION ROUTE FROM THE SITE TO THE NEAREST SURFACE WATER IS APPROXIMATELY 4 MILES AND PROBABLY DOES NOT EXIST DUE TO PAVED ROADS.
- 3. ROSECTED HRS SCORE FOR LSI IS HIGH DUE TO WORST POSSIBLE SCENARIO FOR POTENTIAL RELEASE WHICH IS NOT ADDRESSED AT THE SSI STAGE. FURTHERMORE, CONSIDERING THE HEAVY INSUSTRY IN THE SITE VICINITY,

4. A POTENTIAL AIR RELEASE WOOLD BE DITFICULT TO ATTRIBUTE TO THIS SITE ALONE

5.